

Accessories

Below is a small selection of the accessories available for the Triple Plus+.



Aspirator Kit with Pouch C01685

To enable manual sampling. Includes aspirator bulb, flow plate and 2m of standard sampling hose.



Charger/Interface II international without plug C01440



Charger/Interface II for USA only C01437



Charger/Interface II for UK only C01436



Charger/Interface II for South Africa only C01626



Charger/Interface II for Europe only C01438



Charger/Interface II for Australia only C01439



1 m Rigid Sample Probe
C01097

For sampling remotely eg into chambers during re-entry checks.



Telescopic Sample Probe
C01757

For sampling remotely eg into chambers during pre-entry checks. Extends from 85cm to 155cm.



Standard sampling hose
M04032

Supplied by the metre. Contact sales team for custom length requests.



In line water trap/particulate filter
FIL29001

Protects detector sensors from particles and moisture. Includes filter element.



Replacement water trap filters
FIL99008

Replacement filter elements for FIL29001. (Minimum order 10 elements).



LIBRA Li-ion Battery Upgrade Kit

Upgrade kit for TriplePlus+ and TriplePlus IR units originally fitted with lead acid batteries. Not compatible with original TriplePlus (units with a single battery compartment screw).



Six metre drop line
C03141

Six metre drop line for undertaking pre-entry checks with TriplePlus+.



Carrying case and belt
C01007

Carrying base and belt.




Shoulder strap
C01323

Includes slips to attach to TriplePlus+.



Baffle plate
C01325

Provides additional protection for sensor apertures in extreme conditions, for example by reducing splash and sand ingress.



Top label protective film
M05809

Self adhesive film to provide extra protection to the keypad and display.



Drop-in charger
C011321

Charger with multi-region power supply (includes UK, EU, US, and Australian plug adaptors)



**Ferrite for TriplePlus+ chargers
E01083**

Fit when upgrading non-interface chargers to charge both lead acid and LIBRA battery TriplePlus+ instruments. Note: A ferrite will already be supplied with every new LIBRA powered TriplePlus+ and with every spare LIBRA battery pack upgrade.



**Portables PC Software CD
C01832**

Enables data download, calibration and changes to instrument settings. Requires interface charger (supplied separately).



**Computer lead for TriplePlus+ Interface
C01327**

9 way lead for connecting TriplePlus+ Charger Interface to a PC.



**Vehicle Charging lead
C01296**

For vehicle lighter socket. Use with charger cradle.



**Single sensor calibration adaptor
C01985**

Single sensor calibration adaptor



**Waist belt
C01451**

Waist belt