

Temp. & RH% Datalogger



Temp. + RH% Datalogger (Interface: Cable)

- ▲ Recording temp. and humidity via external probe for quality control
- ▲ Several methods to start recording:
schedule /immediately/repeat/on line/key start
- ▲ 2 ways to program & down load :
 - 1) via PC: USB cable
 - 2) via logger printer 9801: this is a 3 function in 1 printer for programing & download
- ▲ Yellow recording LED indicator
- ▲ Red LED flash while exceeding threshold
- ▲ Can be used as regular temp. & humidity monitor while setting as non-sleep after recording
- ▲ Up to 16000 points memories
- ▲ Powered by lithium battery with long life time
- ▲ Low battery indicator

Optional



EXTERNAL TEMP. & RH PROBE
P/N: VY873PAZ
FOR 88375
COLOR: BLACK
SIZE: 14MM DIA. X 216MM (L)
CABLE: AT MOST 2.5M



USB CABLE
P/N: VZUSBAZD
USB 2.0 INTERFACE
SIZE : CABLE 125CM
-USB CONNECTOR TO PC
-2.5MM DIA. STEREO PHONE JACK TO LOGGER



3 IN 1 DATALOGGER PRINTER
P/N: VZ9801AZ
USB CONNECTOR TO PC
CONNECT WITH 88375 VIA VW302A00 CABLE



LOGGER TO PRINTER CABLE
P/N: VW302A00
SIZE : CABLE 120 CM
-2.5MM DIA. STEREO PHONE JACK TO LOGGER.
-3.5MM DIA. STEREO PHONE JACK TO PRINTER.
THIS CABLE IS A STANDARD ACCESSORY WHILE PURCHASING 9801 PRINTER.

Model	88375
Air temp. range	-20~70°C
Air temp. resolution	0.1°C/°F
Air temp. accuracy	+/-0.6°C (0~50°C), others +/-1.2°C
Humidity. range	0%RH~100%RH
Humidity resolution	0.1%RH
Humidity accuracy	+/-3%RH (at 25°C, 10~90%RH, others +/-5%RH)
Sampling points	16000
Button to on/off	YES
Battery life time	>3 MONTHS
LCD size (mm)	20(H)x40(W)mm
Operating temp.	0~50°C
Operating RH%	Humidity < 80%
Storage temp.	-20~50°C
Storage RH%	Humidity < 90%
Dimension(mm)	90x60x26.5(H) mm
Weight	~100g
Battery	ER3 x 1pc
Standard Package	Meter/Probe/Battery/Manual/Paper box
Optional Accessory	Probe / Software & cable kit /9801 printer

