## **One meter drop-proof "Tested Tough !"** CLAMP ON HITESTER 3127-10



AC Current	6 to 300 A, 5 ranges, (50 to 60 Hz, Average rectified) Accuracy: ±3 % f.s.
AC Voltage	150 to 750 V, 3 ranges, (50 to 60 Hz, Average rectified) Accuracy: ±3 % f.s.
DC Voltage	75 V, Accuracy: ±3 % f.s.
Resistance	$1 \text{ k}\Omega / 100 \text{ k}\Omega$ fuse protected, Accuracy: $\pm 3 \%$ of scale length
T <del>emperature</del> s <del>cale</del>	-50°C to 200°C, Useing range: Ω ×100, Thermister temperature probe 9021-01 required (sold separately) Accuracy: ±3 % of scale length
Power supply	For resistance range: R6P (AA) manganese batteries ×1
Core jaw dia.	φ 33 mm (1.30 in)
Dimensions, mass	78 mm (3.07 in) W $\times$ 190 mm (7.48 in) H $\times$ 34 mm (1.34 in) D, 340 g (12.0 oz)
Supplied accessories	TEST LEAD L9207-30 ×1, R6P (AA) manganese batteries ×1, Spare fuse ×1, Hand strap ×1, Instruction Manual ×1, CARRYING CASE 9351 ×1

Basic specifications (Accuracy guaranteed for 1 year)

Please note: The 3127-10 includes a temperature measurement scale, but because the optional Thermister Temperature Probe 9021-01 has been discontinued, the scale is not available for new customers.

- Drop proof design withstands dropping from a height of 1 meter
- Temperature measurement with optional Thermister probe
- Continuity check is availale with resistance measurement function



## **One meter drop-proof "Tested Tough !"** CLAMP ON HITESTER 3128-10



The maximum permissible circuit voltage : 750 VAC (Insulated conductor)





Basic specifications (Accuracy guaranteed for 1 year)

AC Current	15 to 1500 A, 5 ranges, (50 to 60 Hz, Average rectified), Measurement time up to 2 minuits at over 1000 A, Accuracy: $\pm 3 \%$ f.s.
AC Voltage	150 to 750 V, 3 ranges, (50 to 60 Hz, Average rectified) Accuracy: ±3 % f.s.
DC Voltage	75 V, Accuracy: ±3 % f.s.
Resistance	1 k $\Omega$ / 100 k $\Omega$ fuse protected, Accuracy: ±3 % of scale length
T <del>emperature</del> scale	-50°C to 200°C, Useing range: Ω ×100, Thermister temperature probe 9021-01 required (sold separately) Accuracy: ±3 % of scale length
Power supply	For resistance range: R6P (AA) manganese batteries ×1
Core jaw dia.	φ 55 mm (2.17 in), or 80 mm (3.15 in) width bus bar
Dimensions, mass	99 mm (3.90 in) W $\times$ 237 mm (9.33 in) H $\times$ 34 mm (1.34 in) D, 570 g (20.1 oz)
Supplied accessories	TEST LEAD 9207-30 ×1, R6P (AA) manganese batteries ×1, Spare fuse ×1, Hand strap ×1, Instruction Manual ×1, CARRYING CASE 9148 ×1

Please note: The 3128-10 includes a temperature measurement scale, but because the optional Thermister Temperature Probe 9021-01 has been discontinued, the scale is not available for new customers.

• Drop proof design withstands dropping from a height of 1 meter

Temperature measurement with optional Thermister probe

Continuity check is availale with resistance measurement function

