Phase Indicator 8031

- Phase Indicator with open phase checker
- Phase indicator designed to check the presence of open phase and also the phase sequence by rotating disk and lamps.
- Can check a wide range of 3-phase power source from 110V to 600V.





Standard Type

Operational Voltage	110~600V AC	
Time limit for continuous	>500V: within 5 minutes	
Frequency Response	50Hz/60Hz	
Safety Standa d	IEC61010-1 CAT.III 600V Pollution Degree 2	
Withstand Voltage	5550V AC for 1 minute	
Dimensions	$106(L) \times 75(W) \times 40(D)mm$	
Weight	350g approx.	
Cord	1.5m(R: red S: white T: blue)	
Accessories	9029(Carrying Case)	
	Instruction Manual	